Close

Print

Software Release: ExpressNet® Version 1.51 (Bulletin #8)
Previous Version: ExpressNet® Version 1.50

This new release of software includes the features and enhancements listed below.

THE PROGRAM AND DOCUMENTATION ARE FURNISHED TO YOU "AS IS" WITHOUT WARRANTY OF ANY KIND. PROTEL DOES NOT WARRANT THAT THE PROGRAM OR THE ACCOMPANYING DOCUMENTATION WILL MEET YOUR REQUIREMENTS OR THAT THE OPERATION OF THE PROGRAM WILL BE UNINTERRUPTED OR ERROR FREE. PROTEL DISCLAIMS AND EXCLUDES ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, WITH RESPECT TO THE PROGRAM AND ACCOMPANYING DOCUMENTATION, INCLUDING, BUT NOT LIMITED TO, ANY OR ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

LIMITATION OF LIABILITY
THE PROGRAM AND ACCOMPANYING DOCUMENTATION ARE FURNISHED TO YOU FOR USE AT YOUR OWN RISK. PROTEL WILL NOT BE LIABLE AND YOU WILL HAVE NO REMEDY FOR DAMAGES FOR ANY CLAIM OF ANY KIND WHATSOEVER CONCERNING YOUR USE OF THE PROGRAM OR THE ACCOMPANYING DOCUMENTATION, REGARDLESS OF LEGAL THEORY, AND WHETHER ARISING IN TORT OR CONTRACT. IN NO EVENT WILL PROTEL BE LIABLE TO YOU FOR ANY SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO, COMPENSATION, REIMBURSEMENT OR DAMAGES ON ACCOUNT OF THE LOSS OF PRESENT OR PROSPECTIVE PROFITS, LOSS OF DATA, OR FOR ANY OTHER REASON WHATSOEVER.

Communications
The programs have been modified to prevent them from shutting down as a result of receiving erroneous information from phones that have corrupted data. Previously, if a phone attempted to report to the management software with an excessive number of flags, the program would shut down.

New Firmware Compatibility
The programs have been modified to recognize new firmware versions. The new versions are DD7300 and DD7400. These firmware versions will be used for the 9800 with vacuum fluorescent display and the Ascension phone.

1.51 Update Now Available
INSTRUCTIONS:

1. Download self-extracting executable - XnetV151.EXE - to hard drive.
2. Locate XnetV151.EXE and run. Extract files to floppy drive.
3. Install from floppy disk as usual (previous standard install of ExpressNet® required!).

To Install 1.51 Update, click here.

| Terms of Use | | Contact Us |