

Close

Print

Software Release: ExpressNet® & ExpressNet III® Version 1.55

Release Date: 8/27/01

Previous Version: ExpressNet® & ExpressNet III® Version 1.51

Compatibility: Payphone products using BCXXXX, DAXXXX and DDXXXX firmware

THE PROGRAM AND DOCUMENTATION ARE FURNISHED TO YOU "AS IS" WITHOUT WARRANTY OF ANY KIND. PROTEL® DOES NOT WARRANT THAT THE PROGRAM OR THE ACCOMPANYING DOCUMENTATION WILL MEET YOUR REQUIREMENTS OR THAT THE OPERATION OF THE PROGRAM WILL BE UNINTERRUPTED OR ERROR FREE. PROTEL® DISCLAIMS AND EXCLUDES ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, WITH RESPECT TO THE PROGRAM AND ACCOMPANYING DOCUMENTATION, INCLUDING, BUT NOT LIMITED TO, ANY OR ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

LIMITATION OF LIABILITY

THE PROGRAM AND ACCOMPANYING DOCUMENTATION ARE FURNISHED TO YOU FOR USE AT YOUR OWN RISK. PROTEL® WILL NOT BE LIABLE AND YOU WILL HAVE NO REMEDY FOR DAMAGES FOR ANY CLAIM OF ANY KIND WHATSOEVER CONCERNING YOUR USE OF THE PROGRAM OR THE ACCOMPANYING DOCUMENTATION, REGARDLESS OF LEGAL THEORY, AND WHETHER ARISING IN TORT OR CONTRACT. IN NO EVENT WILL PROTEL® BE LIABLE TO YOU FOR ANY SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO, COMPENSATION, REIMBURSEMENT OR DAMAGES ON ACCOUNT OF THE LOSS OF PRESENT OR PROSPECTIVE PROFITS, LOSS OF DATA, OR FOR ANY OTHER REASON WHATSOEVER.

Phone 1™ International Calling

A table has been added which provides for expanded programming of international country codes. This table is only compatible with phones that are equipped with the Phone 1™ firmware. Up to 290 country/city codes can be assigned in this new table. Each code can then be independently assigned to specific cost bands for call rating.

Communications

The 300-baud modem communication routines have been modified to prevent sending the hang-up command too quickly. If the hang-up command is sent too quickly the phone may not have responded with the date and time of the last successful communication in response to the *#6 reporting command.

New Firmware Compatibility

Compatibility with the Western style Ascension payphones has been incorporated.

Reports

Modifications that prevent a fatal exception error when creating Trouble Reports or Trouble Tickets have been implemented. Previously, a fatal exception may have occurred during the generation of these reports if the Time Overdue flag was selected and the phone is programmed to report using the Day of Month or Day of Week option.

Screen Update

The < F7 - Type > option has been removed from the Call Costing Records Menu (screen 2.2).

The function of this option is no longer supported in the program. At one time, the < F7 > key provided a toggle between CD and DD rate formats.

The text "7000 only" has been removed from references to 1200 baud FSK, disable piezo ringer, and silicon serial number within the Edit Options and Registers screens. These options now apply to other products in addition to the 7000 Series phones.

The text "Credit Express" has been removed from the Programmable Messages title (screen 2257). These programmable messages now apply to other products that feature display messages including the Ascension Series phones.

Electronic Serial Number

The Electronic Serial Number data from the 8000C chassis will now be retrieved and displayed in the Site screen. Previously, the 8000C Electronic Serial Number was not requested.

Communication Error

Communication error 114, "SW/DL fail incompatible types" has been added. This error indicates that the assigned download file is not compatible with the installed chassis.

1.55 Update Now Available INSTRUCTIONS:

- 1. Download self-extracting executable - XnetV155.EXE - to hard drive.**
- 2. Locate XnetV155.EXE and run. Extract files to floppy drive.**
- 3. Install from floppy disk as usual (previous standard install of ExpressNet® required!).**

To Install 1.55 Update, click [here](#).

© 2003 Protel,® Inc. All rights reserved.

[| Terms of Use |](#) [| Contact Us |](#)