



Connection Manager 2.0.0.1

Release Notes

MultiTech Connection Manager Release Notes

Part Number: S000750

Copyright

This publication may not be reproduced, in whole or in part, without the specific and express prior written permission signed by an executive officer of Multi-Tech Systems, Inc. All rights reserved. Copyright © 2019 by Multi-Tech Systems, Inc.

Multi-Tech Systems, Inc. makes no representations or warranties, whether express, implied or by estoppels, with respect to the content, information, material and recommendations herein and specifically disclaims any implied warranties of merchantability, fitness for any particular purpose and non-infringement.

Multi-Tech Systems, Inc. reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of Multi-Tech Systems, Inc. to notify any person or organization of such revisions or changes.

Trademarks

MultiTech and the MultiTech logo are registered trademarks of Multi-Tech Systems, Inc. All other brand and product names are trademarks or registered trademarks of their respective companies.

Support Portal

To create an account and submit a support case directly to our technical support team, visit: <https://support.multitech.com>

Support

Business Hours: M-F, 9am to 5pm CT

Country	By Email	By Phone
Europe, Middle East, Africa:	support@multitech.co.uk	+(44) 118 959 7774
U.S., Canada, all others:	support@multitech.com	(800) 972-2439 or (763) 717-5863

World Headquarters

Multi-Tech Systems, Inc.
2205 Woodale Drive
Mounds View, Minnesota 55112
Phone: 763-785-3500 or 800-328-9717
Fax: 763-785-9874

MultiTech Connection Manager 2.0.0.1

Overview

This document provides a brief summary on the changes implemented in Connection Manager 2.0.0.1.

MultiTech Connection Manager supports USB and serial modems. When using serial modem, Connection Manager requires a standard 33600 bps modem be installed in Windows operating system.

Radio Modem Drivers installation/uninstallation

Connection Manager 2.0.0.1 installation wizard installs modem drivers during installation and uninstalls the drivers during uninstallation process. Connection Manager 1.0.0.67 does not uninstall Telit drivers during uninstallation.

New radio support

Support for the following radio modems was added:

- XXX-L4E1
- XXX-L4G1
- XXX-L4N1
- XXX-LAP3
- XXX-LAT6
- XXX-LDC3
- XXX-LEU3
- XXX-LEU4
- XXX-LEU6
- XXX-LEU7
- XXX-LNA3
- XXX-LNA4
- XXX-LNA7
- XXX-MNA1
- XXX-MNG1
- XXX-MNG2
- XXX-MNG3

Previous radio support

The following radio modems were already supported:

- XXX-C2
- XXX-EV3
- XXX-H5

- XXX-LAT1
- XXX-LAT3
- XXX-LNA4
- XXX-LSP3
- XXX-LVW2
- XXX-LVW3
- XXX-MAT1
- XXX-MVW1

Updated User Interface

Connection Manager 2.0.0.1 has an updated user interface. This change does not affect functionality and settings locations.

Firmware Switch Support

Connection Manager 2.0.0.1 automatically detects modems that support dual firmware image for the following devices:

- Telit XXX-L4N1 / LE910C4-NF
- Telit XXX-MNA1 / ME910C1-NA
- Telit XXX-LNA4 / LE910-NA
- XXX-MNG3 / SARA-R412M-02B
- XXX-MNG1 / SARA-R410M-02B

Connection Manager provides a UI to switch the radio to a specific firmware image (AT&T / T-Mobile, Verizon, etc.). MNO Firmware option is available on the Connection tab and Connection Window if the radio supports multiple firmware images.

Additional Information

For information about installing and using Connection Manager, consult your product documentation.